

### DESCRIPTION:

100% pure acrylic water based paint with silky effect for interior applications. It maintains indoor air quality and keeps it healthy and safe based on **FORMALDEHYDE - LOCK** technology and absorbs formaldehyde coming from its various sources as cigarettes, some furniture, furnishing, carpets and some paints.

### RECOMMENDED USE:

Recommended to be used as silk final coat with smooth touch for absorbing and locking Formaldehyde from air for interior applications on concrete, cement, gypsum and brick surfaces.

### CHARACTERISTICS:

"Al-Jazeera Oxycare" has the following features:

- When there is formaldehyde gas, a reaction occurs between the paint surface and formaldehyde to turn into water vapor.
- Keeps indoor air quality healthy and safe for inhabitants.
- Neutralize the factors affecting the people who suffer from allergy.
- Imparts excellent washability.
- Highly durability.
- Multi colors.
- Excellent wet and dry adhesion.
- Excellent hardness.
- Ammonia and APEO free.
- Very low VOC (Volatile Organic Content)

### PHYSICAL CONSTANTS:

Finish:	Silky finish with smooth touch.
Colour:	Produced in white and other colours of "Al-Jazeera Paints" Colour card.
Gloss:	10±2 at an angle of 60°, ASTM D523.
Specific Gravity:	1.30 ± 0.03 at temperature of 25°C. ASTM D1475.
Viscosity:	93 ± 2 KU at temperature of 25°C. ASTM D562.
Volume Solid:	40 %. ASTM D2697.
D.F.T.:	40 µ each coat.
Theoretical Spreading Rate:	10 m <sup>2</sup> /L (421.1 ft <sup>2</sup> /US gallon) at D.F.T. 40 µ. (To avoid waste, be sure to buy the right amount of the paint for the surface area required).
Water Resistance:	Pass, 7 days, ASTM D870.
Alkali Resistance:	Pass, 7 days (1 % solution), ASTM D1308.
Adhesion:	Pass, ASTM D3359.
Flexibility:	Pass 3 mm. Diameter, ASTM D522.
Freeze-Thaw Stability:	Pass, 3 cycles, ASTM D2243.
Heater Stability:	Pass, 49 days at 50°C.

### SURFACE PREPARATION:

#### New surfaces

-All new surfaces must be cured at least for 30 days prior to application of the primer.

#### For previously painted surfaces:

- Remove old paint from surfaces completely.
- Make sure that the surface is clean, dry, free from dust, oil, grease, salt and mold.
- The surface must be treated by removing all forms release and protrusions to get a suitable surface for application.
- Fill the holes and cracks with suitable fillers "Al-Jazeera Crack Filler" prior to application of the primer.

### APPLICATION GUIDE:

1. The surface must be removed from dust, grease, oil and other contaminants completely.
2. Surface temperature required during application must not be less than 10°C; the surface moisture should not exceed 8% and the relative humidity at work place not to exceed 70%.
3. Maximum pH of 9.
4. Paint should be stirred carefully before use.
5. A suitable quantity of water can be added to get reasonable viscosity for application.
6. Do not apply on wet and moistened surfaces until get completely dry.
7. Do not apply the next coat unless the previous one is fully dry. Minimum recoating interval time should be given between the two coats.
8. Adequate ventilation should be provided during drying time.

### APPLICATION TOOLS:

Airless spray:	Excalibur18601
Nozzle orifice :	0.015 - 0.021"
Nozzle pressure :	15 MPa (150 Bar)
Spray angle :	40-80°
Spray gun:	Recommended nozzle size: (1.5 – 1.8) mm.
Roller :	Recommended type: Soft and smooth woolen roller.
Brush :	General / Normal type.

### THINNER:

Recommended thinner is "Tap Water".

### THINNING RATIO:

- (0 - 5) % by volume for airless spray gun applications.
  - (25 - 35) % by volume for spray gun applications.
  - (15 - 25) % by volume for roller & brush applications.
- Depends on the weather conditions at work place.

### PAINTING SYSTEM:

For interior surfaces:

- Apply one coat of "Al-Jazeera Primex" or "Al-Jazeera C Primer" or any other suitable type of Al-Jazeera Primers and leave for full dry.
- Apply two coats of "Al-Jazeera Easy Putty" then sand the surfaces with sanding paper and clean the dust coming from the sanding by dry cloth or air blower.
- Apply two coats of "Al-Jazeera Oxycare".

### DRYING TIME:

- Surface dry:	45-60 Minutes
- Full dry:	4 hours.
- Recoating interval :	8 hours (minimum).

All above results according to ASTM D5895 @ 25°C.

### CLEANING TOOLS

"Tap Water".

### PACKING:

1 US Gallon.  
Gallon: Base 3 Ltr.( Tint able base by coloring machine).

## AL-JAZEERA OXYCARE

JA-16047

### SHELF LIFE:

In sealed container: 12 months in dry, cool and well-ventilated place.

### SAFETY PRECAUTIONS:

During application of paint, contact of liquid paint with eyes, skin, inhalation of paint mist and paint vapour, should be strongly avoided. When working with paint in in-sufficient ventilated areas, forced ventilation should be provided. For spray application system, eye, skin, respiratory protection are always recommended. Keep away from the reach of children. For environmental safety: please donate the leftover paint and packaging to your local authorized institution for usage or recycling purpose.

Note: Wastes and empty containers should be disposed of in accordance with local regulations made under the Control of Pollution Act and the Environmental Protection Act.

#### Disclaimer

Issued 2014

To the best of our knowledge the technical data listed herein is true and accurate up to publication date and is subject to change without prior notice. User must contact Al-Jazeera Paints Company to verify of any modifications before specifying or ordering the product. Thus, information given in this sheet is not intended to be exhaustive and any person using the product other than the recommendations in this sheet or without reverting to our Al-Jazeera TSD, he should take his accountability in this connection.